



OPS Bulletin

Liquids Prohibited in Passenger Boarding Bridges (PBBs)

June 26, 2019

This OPS Bulletin is a reminder to all airlines and service providers that liquids or beverages of any kind are prohibited inside of the TBIT PBBs.

A spill on the PBB control panel can cause extensive damage on the PLC Units, and the repair will require that the bridge be placed out of service for a potentially significant amount of time.

