



OPS Bulletin

Bridge in Indication (BR IN) Error – VDGS

April 28, 2019

The VDGS BR IN error is an indication of the following: “INCORRECT PASSENGER BRIDGE POSITION” or “PBB IS NOT FULLY RETRACTED”

All Passenger Boarding Bridge (PBB) Operators must ensure that the PBB is secured and properly parked following the guidelines below:

Press and hold down the “PREPOSITION MOVE” button until the status display indicates “Preposition Done” (Auto-park is not completed until the wheels and cab come to a complete rest facing forward).

