



OPS Bulletin

Gate 148 Restrictions for B747-400

April 28, 2019

Gate 148 may not be used for 747-400 operations when Passenger Boarding Bridge (PBB) 2 has been placed out of service.



At Gate 148, when PBB 2 (the second bridge) is unserviceable, PBB 1 cannot be docked to a 747-400 because the proximity of PBB 2 when in a stowed position is an obstruction to PBB 1's path of travel to the L1 Door of a 747-400