



OPS BULLETIN

TBIT Bagroom Cleanliness

There has been a significant increase in the amount of garbage found on sections of the baggage handling system in the TBIT bagroom recently. Service Providers have also been observed sitting on the bag belts while eating their meals.



- These actions increase the general health and hygiene risks for others.
- Puts the BHS equipment at an unnecessary higher risk of failure.
- **Creates a life safety risk for anyone sitting on this equipment. It will start at any time.**

Please report any findings to the TBITEC Duty Manager hotline: 310-646-9378