




OPS BULLETIN

SmarteCartes on the AOA

There has been a significant increase in the amount of SmarteCartes found on the ramp apron areas, bag room, and back office hallways. This poses a huge safety concern as in late 2017 there were reports of a SmarteCarte found in between runway 25L and 25R, which could have resulted in a catastrophe. Additionally LAWA has experienced an increase in warning/citations from the Fire Department as hallways are to be kept free of obstacles in case of an emergency.



Recommended Actions:

- Service Providers and Airline personnel are reminded to brief all their staff that SmarteCartes on ANY area of the AOA are prohibited and subject to a Safe violation by LAWA.
- Hallways are to be kept exit free at all times.

***Please contact the TBITEC Duty Manager Hotline for any questions or concerns at:
(310) 646-9378***